

AMERICAN PROPERTY CONSULTANTS, INC.

A Full Service Inspection, Training, & NSPIRE Software Company

5901 Hillside Road/P. O. Box 98 St. Leonard, MD 20685

2717 Letha Road New Smyrna Beach, FL 32168

Phone (800) 272-7134 Fax (410) 586-1234 E-mail: apcdennis@comcast.net
Web Page: www.HUDPASS.com

NSPIRE POCKET GUIDE ORDER FORM English or Spanish

The NSPIRE ESSENTIALS© Pocket Guide is a condensed version of the well-known REAC Physical Inspector's Field Guide. The NSPIRE ESSENTIALS© pocket guide contains all 63 NSPIRE Standards with Items listed alphabetically; with Observation criteria, with Inspectable Areas: Unit, Inside, Outside, with required corrections times (24, 30, 60, NA) including for HCV; and with the scoring valuation points (2.0-60). This condensed version is great for those who have an understanding of the NSPIRE Standards and need a quick reference guide.





American Propert	y Consultants NSPIRE Essentials - Pocket Guide v3.0			djde
Item	Inspector Notes	Area	HSS	СТ/НСУ
D4	Paint is deteriorated (s.g., pealing, chipping, chalking, cracking, or detached from the substate). Deteriorated paint is more than 20 square feet ("significant").	Outside	Ser	24/301
Private Roads and	Driveways			
01	Road or driveway access to the property is blocked or impassable for vehicles (downed trees, debris, impassable holes, snow banks, parked cars, or flooding)	Outside	Ser	24/308
D2	One pothole that is 4 inches deep and 1 square foot or greater	Outside	Mod	30/30
Refrigerator				
D1	Unable to safely and adequately store food	Unit	Mod	30/308
D2	Component is damaged such that it impacts functionality (seal that is hanging, sagging, separating, torn with exposed magnet, or detached from the door; handle; interior lining	Unit	Mod	30/30
D3	Missing (AHR)	Unit	Mod	30/30
Retaining Wall	(if it is not at least 24 inches, then it is not subject to inspection.)			
D1	Retaining wall is leaning away from the fill side		Mod	30/308
02	Retaining wall is partially or completely collapsed		Mod	30/30
Roof Assembly				
DI	approximately 25 square feet of ponding water is located above the drain		Mod	30/30
02	Gutter component is damaged, missing, or unfixed	Outside	Mod	30/30
D3	Water ponding in 25 square feet or greater not near a drain or scupper	Outside	Mod	30/308
04	Substrate is exposed (missing or damaged shingles, tiles, or membrane)	Outside	Mod	30/30
DS	Unintentional hole of any size is found; Intentional hole of any size is found and is not covered by a vent or screen (soffits, eaves, fascia, and roof decking)	Outside		30/30
	Roof assembly is damaged	Outside	Mod	30/30
Sharp Edges				
DI	Can result in a cut or puncture that is likely to require emergency care (normal paths of travel throughout the built environment: unit; hallways, shared facilities; sidewalks, walkways, playsrounds, courtvards)	Unit Inside Outside	Ser	24/30

How to Order Pocket Guides:

Phone: 800-272-7134 Online: www.hudpass.com Fax: 410-586-1234

Email: apctoni@comcast.net

Mail: American Property Consultants PO Box 98 St. Leonard, MD 20685

Copy form if mailing; Checks payable to American Property Consultants, Inc.

Item	Price	Quantity	Total Price					
NSPIRE ESSENTIALS© Pocket Guide	\$14.95							
NSPIRE ESSENTIALS © Spanish Pocket	\$14.95							
Guide								
Shipping & Handling Fees	1 Guide	\$7.00						
	2-3 Guides	\$9.00						
	4-10 Guides	\$12.00						
	11 & up Guides	Call for Pricing						
Total								
Name:								
Organization								
Shipping Address:								
Phone & Email:								